CHURCHES

LOCATED ON PARK AVENUE

Star of Isreal Synagogue
115-116 Park Avenue

United Synagogue

115 Park Avenue

AMD SHLATHO STRUCTURES: NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # /4-7 INDIVIDUAL STRUCTURE SURVEY FORM

HISTORIC NAME: Public School #7 COMMON NAME: Lunar Fashions

LOCATION: First Street and Park Avenue BLOCK/LOT: 22/11

80-84 Park Avenue

MUNICIPALITY: Hoboken (251-59 Newark) __UNTY: Hudson _____ Saburban | | Websul | Residential | | Egricultural []

OWNER/ADDRESS:

ORIGINAL USE: School

USGS QUAD:

Downtown Commercial [] Highway Commercial [] Other [PRESENT USE: Clothes Factory

DESCRIPTION

Construction Date: 1887

Source of Date: Bicentennial Comes To

Hoboken

SIGNIFICANCE:

Architect:

Builder:

Classical Revival

Number of Stories: Four with tower

Foundation:

Form/Plan Type:

I Japiles VI

Structural System:

Exterior Wall Fabric: (Lime stone? or gray concrete bricks) first story;

yellow (Roman) brick above

Fenestration: Arched transoms on top story, other windows are double hung

Entrance Location:

Roof/Chimneys:

Additional Architectural Description:

Tower massing over entry and palladium motif at top; tower windows blocked up with concrete blocks; copper gutters and eaves.

DECEMBER STATES STATES TO THE FOREST STATES STATES STATES STATES

Sholee

Good [] Fair [] Poor []

Roads [] Development [] Contact [] Deterloration

MAP (Indicate North)

PETSICAL COMPTION:

TERRATE TO STRUCTURE: Mo Pintest [] Other




photo dute: 10-10-78

COMMON NAME: Fashions	COMPANIAL PROPERTY OF THE PROP
SURROUNDING ENVIRONMENT: Open Space [] Woodla Suburban [] Urban [] Residential [] Agric Downtown Commercial [X] Highway Commercial []	and [] Scattered Buildings [] cultural [] Industrial [] Other []
Source of Late:	DESCRIPTION Construction Date:
Builder	Architecti
One of a number of former public s Massive, impressive appearance.	school buildings in Hoboken.
	Structural Synthes
	Exterior Wall Fabric:
le h	Penestration: Archite
	Parrance Location:
	Roof/Chiameye:
a man, in the are from	Additional Architectural Desc
. Soridra	per and sewer
A May 18 ft and a data day on the control	w or bestol swobury
REGISTER ELIGIBILITY: Yes [] Possible [] I THREATS TO STRUCTURE: Roads [] Development [No Threat [X] Other [] COMMENTS:] Zoning [] Deterioration [
Control of the Contro	1-11
Hole cut in facade to facilitate d	delivery.
Hole cut in facade to facilitate o	elivery.
	elivery.
REFERENCES:	
REFERENCES:	

SITING AND RELATED STRUCTURES:

RECORDED BY:

ORGANIZATION: CDA DATE: 7-78

J. P. Sholeen

7-78

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # STREETSCAPE SURVEY FORM

STREET NAME: Park Avenue MUNICIPALITY: Hoboken

CROSS STREETS: Newark Street and Observer COUNTY: Hudson Highway

DESCRIPTION/SIGNIFICANCE:

Commercial and residential street. Storage warehouse facilities on Observer Highway; vacant lots in middle of East Side, south end of West Side.


Conditions - fabrics of neighborhood is destroyed by random demolition and development; only six apartment buildings remain, vacant.

College VI

STREETSIDE BLOCK

INDIVIDUAL SITES:

PHYSICAL CONDITION OF SITES: E cellent % Good 60% Fair 40% Poor % REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [X] THREATS TO SITE: Roads [] Development [XX] Zoning [] Deterioration [] No Threat [] Other [] COMMENTS:



INDIVIDUAL SITES:

X (STORY X BAYS)

STRRET NAME: Holiday Fashions Inc. - warehouse and vacant lot

63-69 Four apartment units; 65 is vacant

Kalaine upholstery; two story brown brick

vacant lot on northeast corner

WEST SIDE

Vacant lot with fence; takes up more than 1/3 of wouthend of block.

Two apartment buildings, 5X4 same scale as across street; slightly different lintels and cornices.

72 Auto Body Shop, one story parking lot

Ex public school 7 (Lunar Fashions) See individual form.

PHYSICAL COMDITION OF SITES: E cellent . Z Cood Z Fair Z Poor RECISTER FLIGHBILITY: Yes [] Possible [] No [] Part of larger district [] THREATS TO SITE: Roads [] Development [] Soning [] Deterioration [] No Threat [] Other []

MAP (Indicate Worth)

REFERENCES:

RECORDED BY: Jeff Sholeen ORGANIZATION:

DATE: 8/50

SIAIR SIRE

WEST SIDE




56-66 Park Ave. neg. #14-3



68 Park Ave. neg. #14-4



70 Park Ave. neg. #14-5



#72-74 neg. # 14-6

photo date: 10-10-78



71-75 Park Ave. neg. #12-11



#69, #67 neg. #12-10



neg. #12-9



#55-57 neg. #12-8

JERSEY DEPARTME

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # STREETSCAPE SURVEY FORM

STREET NAME: MUNICIPALITY: Park Avenue

Hoboken

CROSS STREETS: Newark and First Streets

she is upon

COUNTY: Hudson

DESCRIPTION/SIGNIFICANCE:

Residential and commercial uses. East side of block has vacant lot at south end with various one or two or three story frame buildings.

PHYSICAL CONDITION OF SITES: E.cellent % Good 40% Fair 60% Poor REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [X] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration [] No Threat [x] Other [] COMMENTS:

Wood cornices need repair (86,88)


REFERENCES:

MAP (Indicate North)

9 37

11 15

1. 1. 1. 1. 1. 1.



EAST SIDE VACTURE STREETS DIROTEN MOITAVANEETS DIROTEN TO MOITAVAN TO MOITAVAN

_STORY, __ BAYS (_X_)

Vacant lot
89-91 Two story building, wood with asphalt brick sheathing; cornice with tin plating appears to be tiled; also has "Deeper Life Deliverance" Church.

93(?) One story Spanish-American Barbershop

95(?) Brick veneer first story; abandoned S.F. faces First Street; Asphalt sheathing second and third story; intact cornice.

WEST SIDE

Two four story apartment buildings

86 4X3 fairly intact S.F.

4X4 lintels and cornices match

North 2/3 of block - Scardino Clothing Enterprises, Liquor Store faces First Street

PHYSICAL COMDITION OF SITES: E cellent 1 Cood of Fair T Poor 1
REGISTER ELIGIBILITY: Yes [] Possible [] Wo [] Part of Larger district []
Wo Threat [] Other [] Davelopeson [] Zoning [] Deterforation []
COMMENTS:

MAF (indicate North)

REFERENCES:

STATE

12000

SKESERVATION,

STREET NAME: MUNICIPALITY:

EAST SIDE



95 Park Ave. neg. # 12-13



#93,91-89 neg. # 12-14

WEST SIDE



86-88 Park Ave. Neg. # 14-8



#90-98 neg. # 14-9

photo date: 10-10-78

NEW

new Jersey Office of Historic Preservation Historic Sites inventory 🖸 STREETSCAPE SURVEY FORM

STREET NAME: Park Avenue MUNICIPALITY: Hoboken

CROSS STREETS: First and Second Streets

COUNTY: Hudson

DESCRIPTION/SIGNIFICANCE:

Basically residential block with many 3X3 row houses. Commercial uses relate to First Street. West side characterized row housing set far back from street


with deep front yards.

PHYSICAL CONDITION OF SITES: E.cellent 30% Good 65% Fair 5% Poor REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [x] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration [] No Threat [] Other [] COMMENTS:

REFERENCES:

(Indicate North)

1.7



EAST SIDE YROTHSVHI SHTIS DIROTSIN HOITAVARISHT SIRGISH TO TOISTO THANKS WHEN THE TRANSPORT OF THE PROPERTY OF

STOREFRONT (S.F.)

STORY, BAYS (X) TIME

Park Fashions, three story commercial building with recent (postwar) alterations to first two stories; faces First Street; then vacant lot.

111 3X3 lone rowhouse
United Synagogue of Hoboken (see individual form);
vacant lot (Synagogue lot?).

123-35 3X3 rowhouses with areaways and curved brick lintels; 123,25,31,33 altered with new brick facades.

137,39 Altered 3X3 buildings

WEST SIDE

100 Four story white brick altered faces First Street.

102 Red brick garage with patterns in yellow brick

104-10 3X3 italianate; 108 has new yello brick veneer with no cornice; 110 refaced with aluminum siding.

112 Somewhat taller than others.

Deep front yards; 114,16,20,22 appear to be similar although 122 seems to have any intact facade elements; 118 is three story; protrudes out toward street; 124,26, three story; altered with brick and aluminum siding; 128 looks basically intact; leans to left; 130 particularly small; 132 aluminum siding (originally same as 114,16,20,22; 134 aluminum siding; 136 masonite siding with gable and roof.

138 4X3 corner building with altered S.F.

PHYSICAL COMDITION OF SITES: E cellent I Good I Peir I Poor I SECISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [:] THERATE TO SITE: Roads [] Development [] Zoning [] Deterioration [] No Threat [] Other []

(fireW s.s. dead)) deed

REFERENCES:

MISLOMIC

COMMENTS:

STREET NAME:

MUNICIPALITY: 1050 CCB

WEST SIDE




100,102,104,106 Park Ave. neg. # 14-10



104,106,108 Park Ave. neg. # 14-4



110,112,Park Ave. neg. # 14-12





114,116,118 Park Ave. n eg. # 14-13

WEST SIDE



Mary Mary San San

we had diedly

120,122,124,126 Park Ave. neg. # 14-14



128,130,132,134,136 Park Ave. neg. # 14-5



138 Park Ave. neg. # 14-16



139,137,135 Park Ave. neg. # 12-20



135,133,131,129 Park Ave. neg. # 12-19



127,125,123 Park Ave. neg. # 12-18

(609)292-2023

DEP/ OFFI

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # /2-17 INDIVIDUAL STRUCTURE SURVEY FORM

HISTORIC NAME:

LOCATION: 115-17 Park Avenue

COMMON NAME: Star of Israel Bldg.

177/617 BLOCK/LOT

MUNICIPALITY: Hoboken

USGS QUAD:

OWNER/ADDRESS: UNITED SYNAGOGUE OF

HOBOKEN/830 HUDSON ST.

COUNTY: Hudson UTM REFERENCES:

Zone/Northing/Easting

DESCRIPTION

Construction Date:

Source of Date:

Architect:

Builder:

Style: Eclectic-Gothic, Islamic,

Russian

Form/Plan Type:

Number of Stories:

Foundation:

Exterior Wall Fabric: Yellow brick & stone front, concrete


stucco on sides.

Fenestration: Pointed arched windows, all windows are stained glass.

Roof/Chimneys:

Additional Architectural Description:

Fence - (donated by Chas. Scweller, 1923) with Star of David motifs. Double entry with 3 windows above in 2nd story and single window in 3rd story (only round-arched window on bldg.) 2 copper onion dowles give tower-like effect at top of front corners.






photo date: 10-7-78

SITING, BOUNDARY DESCRIPTION, AND RELATED STRUCTURES:
Slightly taller than neighboring buildings and across from houses with large front yards. Dominates block due to unusual style.
with large front yards. Dominates brock due to unusual style.
LOCATION: LIB-11 Face
MENTGLEALITY
 CENCES OUTD:
 SURROUNDING ENVIRONMENT: Urban [] Suburban [] Scattered Buildings [] Open Space [] Woodland [] Residential [] Agricultural [] Industrial [] Downtown Commercial [] Highway Commercial [] Other []
Some light industrial & warehouse activities.
100 AC
SIGNIFICANCE:
Unusually florid design for Hoboken with interesting glass and domes. Brick is of a type that was common in the 1920's.
,
ORIGINAL USE: PHYSICAL CONDITION: Excellent [X] Good [X] Fair [] Poor [] REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of District [X] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration []
No Threat [X] Other [] COMMENTS:
Services now held at 830 Hudson (according to sign on door) but this building is well-maintained.

RECORDED BY: J. Shaleen ORGANIZATION: CDA

REFERENCES:

DATE: 1978

EAST SIDE



117-115,111 Park Ave. neg. # 12-16



107-101 Park Ave. neg. # 12-15

NEW

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # STREETSCAPE SURVEY FORM

STREET NAME: Park Avenue MUNICIPALITY: Hoboken

CROSS STREETS: Second and Third Streets

COUNTY: Hudson

DESCRIPTION/SIGNIFICANCE:

Predominantly residential block with some commercial intrusions. Buildings mostly three and four story Italianate with variety of facades. Great variety in height is evident. One-two foot gaps between houses on West Side.

Intact details at: Doorways - 204, 206, 228 Fences - 219, 222 Rails - 210, 219, 222


PHYSICAL CONDITION OF SITES: E.cellent % Good % Fair % Poor % REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [%] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration [] No Threat [] Other [] COMMENTS:

REFERENCES:

MAP (Indicate North)

TWO CONTRACTOR

1. 2 16



STOREFRONT (S.F.)

STORY, BAYS (X) TIMUO

STREET NAME: DESCRIPTION OF THE STREET NAME OF THE STREET NAME OF THE STREET OF THE ST

rect	205,07	Lots #1 and #3 are vacant. Two 4X3 Italianate buildings
		4X3 Italianate; two buildings share fire escape.
	215	On three lots (13-17); two story 1965 apartment building
	219	Five story apartment building with two tripartite oriels; yellow
		brick with sheet metal oriels.
	221	Garage; (one story)
	223,25	3X3 Italianate pair
	227	Cast iron columns are intact; first story of 4X3 building altered with green brick.

4X3 first story cast iron pillars also intact here.

231 3X3 with yellow brick veneer

233,35 Two single Greek Revival; six over one windows.

WEST SIDE

(Arrow a Morth)

		11 20 12
	200	Two story; Italianate; S.F. faces Second Street.
	202	Altered Italianate; new parapet; with original lintels.
		(No 206) Two 4X4 apartment units; altered with white brick.
	210	Altered with yellow brick.
	212	Signal and Traffic Division; originally fire station; Romanesque
		arches; stripped cornice.
	214	Five stories with a pair of triple oriel windows flanking single
		arched windows with scallops. That have shell motif.
	218	Simple 3X3 Italianate
ceres	220	4X3 with intact cornice
		Pair of 3X3 Greek Revival Rowhouses; cornice removed at 222.
		2X3 Bay with yellow brick.
	228	3X3 Italianate with altered S.F.; intact wood clapboard siding
		on side facade.
	230	5X4 with brown (stone?) first story, red brick above, stone lintel
		with stone courses, arched top windows and brick corbelling under
		cornice.
	232	5X4 cast iron pillars intact in first story only remaining detail
		of altered first story.
	234	5X4 Fire escape; same lintels as 232; completely altered S.F.

A 1C

REFERENCES:

DEP, OFF1

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # INDIVIDUAL STRUCTURE SURVEY FORM

HISTORIC NAME:

Engine Co.#4

COMMON NAME:

LOCATION:

212 Park Ave.

165/29 BLOCK/LOT

MUNICIPALITY: Hoboken

Hudson COUNTY:

USGS QUAD:

OWNER/ADDRESS: City of Hoboken

UTM REFERENCES:

Zone/Northing/Easting

DESCRIPTION

Construction Date: pre 1870

Source of Date: fire station records

Architect:

Builder:

Style:

609) 292-2023

vernaculær Italianate

Form/Plan Type: rectangular

Number of Stories:

Foundation:

Exterior Wall Fabric: stretcher bond facade, painted pink

load bearing masonry construction

Fenestration: 3 bay, one/one lights, stone sills, round arch windows

second floor with brick voussoir

Roof/Chimneys: flat roof

Additional Architectural Description:

Cornice removed.

Two large raised brick arches top facade wall

and span width of building.


Arches above windows are raised and end in drops

with incised ornament.

Fire engine door is centered and is flanked by

fluted pilasters.

PHOTO Negative File # SIGNAL & TRAFFIC-DIVISION # HOBOKEN, N.J.



SITING, BOUNDARY DESCRIPTION, AND RELATED STRUCTURES:

Situated on the west side of a city block which is surrounded by buildings of similar height.

SURROUNDING ENVIRONMENT: Urban [] Suburban [] Scattered Buildings [] Open Space [] Woodland [] Residential [] Agricultural [] Industrial [] Downtown Commercial [] Highway Commercial [] Other []

SIGNIFICANCE:

According to the fire department sources, the station is the oldest firehouse in the city which is still standing. It is similar in style and size to the firehouse at 213 Bloomfield.

PRESENT USE: Police and fire Fair [] Poor [] Signal, D ORIGINAL USE: fire station
N: Excellent [] PHYSICAL CONDITION: Good [X Part of District [] Dept REGISTER ELIGIBILITY: Yes [A] Possible [] No [] Roads [] THREATS TO SITE: Development [] Zoning [] Deterioration [] No Threat [X] Other [] COMMENTS:

Could be part of a thematic nomination of Hoboken's fire houses

REFERENCES:

Fire Department memorandum -- Dates of Fire Stations Interview with deputy chief officer James Halloran and Patrica Florio.

RECORDED BY: Michael S. May ORGANIZATION: Columbia University

DATE: May 4, 1980



200, 202 Park Ave. neg. # 14-17



204,208,210 Park Ave. neg. # 14-18



212,214 Park Ave. neg. # 14-19



218,220,222,224 Park Ave. neg. # 14-40

photo date: /0-/0-78



226,228 Park Ave. neg. # 14-21



232,234 Park Ave. neg. # 14-23



230,232 Park Ave. neg. # 14-22

photo date: /0-/0-78



235,233,231 Park Ave. neg. # 12-27



229,227 Park Ave. neg. # 12-26

photo date: /0-7-78

225,223,221 Park Ave. neg. # 12-25



219 Park Ave. neg. # 12-24



211,209 Park Ave. neg. # 12-23



207-205;203-201(lot) Park Ave. neg. # 12-21

photo date: 10-7-78

JERSEY.

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # STREETSCAPE SURVEY FORM

STREET NAME: Park Avenue MUNICIPALITY: Hoboken

CROSS STREETS: Third and Fourth Streets

COUNTY: Hudson

DESCRIPTION/SIGNIFICANCE:

Varied facades; mostly 3X3, fairly uniform cornice heights. is painted brick, often red. Buildings remain but there are quite a number of alterations that are out of character with intact Enough detailing remains to make the block of some historical The block looks well maintained in its present state. interest.

The fact that Church Square is directly north of this block also adds to the block's appearance and gives this streetscape added importance. (which makes the preference for unsympathic rehab - aluminum siding, brick veneer, permastone, etc. - all the more unfor tunate.

Intact doors: 304, 330, 332

PHYSICAL CONDITION OF SITES: E.cellent 80% Good 20% Fair Z Poor REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [X] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration [] No Threat [X] Other [] COMMENTS:


Restoration would be worthwhile because of the close proximity of Church Square.

REFERENCES:

(Indicate North)

AND CARREST

44 7 365



NEW JEASET OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY STOREFRONT (S.F.) STREET WANK: STORY, BAYS (X) MUMICIPALITY: COUNTY 301 4X3 Altered with yellow brick. 303 Three story asphalt sheathing. DESCRIPTION/SIGNIFICANCE: 305 3X2 parapet, no cornice 307 3X3 3X3 slightly different variations on designs in 301-7. 309 Three story altered permastone and masonite siding (No 313) 311 315 Two story doctor's office with residence; 1970's modernization, . Jaquely mediterranean in style. 317 Three story with garage in first story; looks like original S.F. cornice removed. 319 2X3 aluminum siding. 321 Second story casement windows; garage. 323-33 Altered with brick and enamelled metal panels in first story. Fenestration changed; false brick in 325 and 327; white brick veneer on 333. 335 - 39Simple conrices. 341 3X3 343 Altered with aluminum siding. WEST SIDE Five story, two paired, one single window in each bay; intact S.F. 300 cornice and second story oriel. 3X3 altered first story in each, slightly different cornices. 302,4 Two 3X3 buildings; stripped cornice; false brick front. 306,08 Two story 1960's apartment buildings, fiberglass siding. 310,12 314-16 3X3 Italianate with high basement. FRYSICAL COMDITION OF SITES: E cellant % Good E Vacant lot.

318,20

(dirok siso

3X3 intact (except doors) states of 1 ask synthis sand sand 322

3X4 parapet; segmental arch lintels. 324 326 Completely altered; green pebbles on stucco.

328 Cornice removed.

Three story, three and five bay units respectively with intact 330,32 doors.

334 Pizzeria in areaway.

336 Mottled orange brick alteration.

338 Permastone with false brick sheet metal above.

340 Altered first story; oriel above.

REFREENCES:

BEGIECET

BANK

MEST

100

38E

RIEZORIC



300-302-304-306-308 Park Avenue neg. #14-24



302-304-306-308 Park Avenue neg. #14-25



310, 312, 314, 316 Park Avenue neg. #14-26



318, 320 (vacant), 322, 324 Park Avenue neg. #14-27



326, 328, 330 Park Avenue neg. #14-28



330, 332 Park Avenue neg. #14-29



334, 336, 338 Park Avenue neg. #14-30



338, 340 Park Avenue neg. #14-31



343, 341 Park Avenue neg. #12-35



341, 339, 337 Park Avenue neg. #12-34



335, 333, 331 Park Avenue neg. #12-33



329, 327, 325 Park Avenue neg. #12-32



323, 321, 319, 317 Park Avenue neg. #1231



315, 313, 311 Park Avenue neg.#12-30



309, 07, 05 Park Ave neg. #: 12-29



307, 05, 03, 01 Park Ave. neg. #: 12-28

NEN

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # STREETSCAPE SURVEY FORM

STREET NAME: Park Avenue MUNICIPALITY: Hoboken

CROSS STREETS: Fifth and Sixth Streets

1775 727

97.2 33

COUNTY: Hudson

DESCRIPTION/SIGNIFICANCE:

Buildings characterized by three and four story heights, brick facades. The West Side has greater variety, as one side of library takes up four lots at south end. Only five apartment units remain; others apparently torn down for the post 1970 construction of Public School #4.


The library dominates its corner but faces Church Square, i.e. it does not strongly relate to the park streetscape. Still the square and the view from the park toward the street are important. The street is much more intact than Park Avenue between Third and Fourth Streets across the square.

Intact Doors: 505,506,507,509, 519,521,523,527,529,531.

PHYSICAL CONDITION OF SITES: E.cellent 70% Good 30% Fair % Poor % REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration [] No Threat [] Other [] COMMENTS:

REFERENCES:

MAP (Indicate North)



HEW JEASEY OFFICE OF WISTORIC PRESERVATION HISTORIC SITES INVENTORY STREETSCAPE SURVET FORM

STOREFRONT (S.F.) STORY BAYS (X) STREET WAME: PA MUNICIPALITY: HO COUNTY: 501 Side of three story building facing Fifth Street. 503 Short three story building with segmental arch lintels. Segmental arch curved lintels; 3X3 505-09 511 513,15 False brick (original matched 505-09) 517,19 Flat lintels 3X3 521 Altered white brick Vencer? or applied false brick? 523 Altered with yellow brick 525 Segmental arch lintels 527,29 Segmental arch lintels; altered S.F. at 527 531 Elaborate lintels; pedimented cornice; brick courses 533,35 Italianate pair 3X3 One 5X7 building; altered S.F. 537,39 WEST SIDE Hoboken Library facing Fifth Street; North end of building houses 500-06

1 P 15 795 90	school for industrial education; (See individual form)
508	Brown brick; post 1960 (Salon del Reino; Testicos de Jehona)
510	4X3 Italianate; segmental arch lintels
512	Permastone; lintels match 510
514	4X4 apartment building
516,18	Pair of 4X4 blocks
520	Vacant
524.	Public School #4; materials concrete; striated finish on front
524 (528) 532	Vacant lot
532	Side of four story block facing Fifth Street
62	TOO TOO TO THE TO AND TOO TOO TOO TOO TO TOO TO THE TOO TOO TO THE TOO TOO TOO TOO TOO TOO TOO TOO TOO TO

named a towall

idarch estes ball) Who

No [] Part of larger district []

for its [] Derertoration []

REFERENCES

COMMENTS:

RECISTER BLICIBILITY: Yes [] Fossibl

THERATS TO SITE: Roads []

Ho Threat | 1 Other []

DIA

OF SHAIFOMMEMIVE SBOLECLION'S

MEST STATE

T03

HISLORIC SEERENALION'



508, 510, 512, 514 Park Avenue neg. #14-33



514, 516, 518 Park Avenue neg. #14-34



524 Park Avenue - Public School No. 4 neg. #14-35



524 - 532 Park Avenue neg. #14-36



532 Park Avenue neg. #14-37



539, 537 Park Avenue neg. #13-7



.535, 533 Park Avenue neg. #13-6



531, 529 Park Avenue neg. #13-5



527 Park Avenue neg. #13-4



525, 523, 521 Park Avenue neg. #13-3



519, 517, 515 Park Avenue neg.#13-2



513, 511, 509 Park Avenue neg. #13-1



507, 505, 503 Park Avenue neg. #12-37



509, 507, 505, 503, 501 Park Avenue neg. #12-36

08625

O.

NEN OF

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # STREETSCAPE SURVEY FORM

STREET NAME: Park Avenue MUNICIPALITY: Hoboken

CROSS STREETS: Sixth and Seventh Streets

COUNTY: Hudson

DESCRIPTION/SIGNIFICANCE:

Block of three story Italianate rowhouses with some form core of block while over ½ of the East Side consists of circa 1960 two story units with basement garages, that intrude both in terms of scale and of materials (light color brick).

The WEst Side has a more homogeneous rowhouse appearance, although there are a number of taller tenement buildings. Also notable is the Martha Institute which faces Sixth Street, although the side facade on Park Avenue has the few remaining round arched windows.

Intact Doorways: 602, 606, 616, 615, 622, 624, 634


PHYSICAL CONDITION OF SITES: E.cellent50 % Good 40% Fair10 % Poor REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [X] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration [] No Threat [X] Other [] COMMENTS:

REFERENCES:

MAP (Indicate North)

9 Mil . 19 24 M 1977

11.7 20



HEAST SIDE THOTHER STILL STREET HOLD HISTORIC SITES TATENTORY STREETSCAPE SURVEY FORM

STOREFRONT (S.F.)

STORY BAYS (X)

601-07 Martha Institute faces Sixth Street (See individual form)
609-13 Four story Italianate apartment buildings; segmental arch doorway;
lintels on 611,13; 609 and 611 are each 4X3; 613 is 4X4; all
altered with brick; white on 609; yellow on others; cornice
stripped 611 and 613.

615 Simple Italianate 2X3

617-39 Eleven modern (c.1965) two story buildings, paired units (except 639) with basement garages.

WEST SIDE

Side of Italianate facing Sixth Street.
Five story apartment building with bay window and fire escape.
2X3, no cornice; parapet
3X4 Italianate building; S.F. cornice intact; heavy lintels.
608,10 608 detailing matches 606; 610 altered with white brick.
2X3 covered cornice.

614 2X2 very narrow building.

5X4 stone courses. 618 Vacant with garage

Two entrances, stained glass; classical revival, intact fire escape; intact on right side, lintel with false voussoirs; heavy copper cornice.

626,28 3X3 Italianate corner stone on right basement. 630-38 Segmental arch lintels, except altered on 630.

4X3 similar details to 630-38, but with S.F.

TisT T

RECISTER ELICIBILITY: Yes [] Foreignes [] Fort of larger district [] THREATS TO STITE: Roads [] Development [] Route [] Decentoration [] Forthers:

PHYSICAL COMMITTION OF SITES: R cellags I Conde

(discon essential

REFERENCES

27 A 7 B

MESSA

109

SKERRANTIONS

MISIORIC

SIRERT NAME:

MUNICIPALITY




600,602,604.606 Park Avenue neg. #17-18



602 Park Avenue neg. #17-19



606, 608, 610 Park Avenue neg. #17-20



612, 614, 616 Park Avenue neg. #17-21



622 - 624 Park Avenue neg. #17-22



626, 628, 630 Park Avenue neg. #17-23



632, 634, 636 Park Avenue neg. #17-24



636(part), 638, 640 Park Avenue neg. #17-25

637 - 619 Park Avenue neg.#13-12





619, 617, 615 Park Avenue neg. #13-11



613, 611, 609 Park Avenue neg. #13-10

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # STREETSCAPE SURVEY FORM

STREET NAME: Park Avenue MUNICIPALITY: Hoboken

CROSS STREETS Seventh & Eighth Streets

COUNTY: Hudson

DESCRIPTION/SIGNIFICANCE:

Basic character 2X2 on East Side, 3X2 brownstone on West Side. Taller buildings on North and South end of East Side and North end of West Side. West Side not as well kept up as East Side. East Side much more intact, buildings in better condition.

Intact details:

Rails: 703,05,06,10,15,17,21,25,27,32,34,38,42,44,46

Fences: 703,05,10,15,17,21,26,27,32,34, 38,42,44

Transom Glass: 710 Window Grillwork: 706

Doors: 703,05,11,13,15,17,21,25,27,29,30,32,34,39,42,44


PHYSICAL CONDITION OF SITES: E.cellent45 % Good 45% Fair 10 % Poor % REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration [] No Threat [xx] Other [] COMMENTS:

REFERENCES:

MAP (Indicate North)

1 VO. M. Rap off a

27.7



MUNICIPALITY:

STORY, BAYS (X) COUNTY

- 701 Circa 1960 apartment building faces Seventh Street.
- 703 Five story with two-three part copper bays.
- Brick with brownstone trim, 4 stories with bay window. 705
- 707-29 2X2 brick rowhouses with high basements and areaways; brownstone trim with brick courses; those at lintel level set corner out; many intact stairways; all cornices intact.
- 731 Altered, no cornices.
- 733 Italianate with particularly heavy lintel over door; 3X3 building
- 735,37 Vacant
- 739 3X3 Italianate.
- 741 Shorter but detail matches.
- Curved lintels; altered S.F. 743

WEST SIDE

- 700 4X3 curved lintel, altered S.F.
- 702,04 2-2X2; Two covered cornice; permastone on right; stucco and parapet.
- 706,08 Pair of 3X3 Italianates
- 3X2 brownstones; only 720 intact; others have cement; 714 stucco 710-20 and 716 permastone.
- 722,24 2X2 Italianates; detailing
- Same as 710-20, intact except for stuccoed fronts at 730,32. 726-40
- 5X4 apartment building; Italianate with stone courses in need 742 of paint.
- 744 Suggests Classical Revival style; arched windows, first and fourth stories. 5X4
- 5X4 Classical Revival; altered S.F. 23718 to MOITICKED LASIETAS RECISTER BENGISLLIFT: Yes [] Posible [] For [] Part of larger district THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration []

PAP (Indicate Morels)

REFERENCES:

COMMENTS:

00 MESS

SEREEBAVILOM

No Threat | | Other []



700, 702, 704, 706 Park Avenue neg. #17-26



702, 704, 706(part) Park Avenue neg. #17-27



706, 708 Park Avenue neg. #17-28



710, 712, 714 Park Avenue neg. #17-29



716, 718, 720, 722 Park Avenue neg. #17-30



720(part), 722, 724, 726 Park Avenue neg. #17-31



726, 728 Park Avenue neg. #17-32



728, 730, 732, 734 Park Avenue neg. #17-33



734, 736 Park Avenue neg. #17-34



738-740 Park Avenue neg. #17-35



742, 744, 746 Park Avenue neg. #17-36



744, 746 Park Avenue neg. #17-37

40

NEW OFF

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # STREETSCAPE SURVEY FORM

STREET NAME: Park Avenue MUNICIPALITY: Hoboken

CROSS STREETS: Eighth and Ninth Streets

COUNTY: Hudson

DESCRIPTION/SIGNIFICANCE:

Residential block; five story buildings on East Side; three story buildings on West Side. East Side has large elementary school, end of block, which faces Ninth Street (see individual form).

Towards North end of West Side, a break occurs where two buildings

have front yards.

The less well kept nature of the block, a tendency that seems to go along with tenements, sets it apart from the less densely built and better maintained nature of nearby blocks on Park Avenue and Garden and Bloomfield Streets.


Intact doorways: 800,02,04,06,16,19,26,42

PHYSICAL CONDITION OF SITES: E.cellent35 % Good 40% Fair25 % Poor REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration [] No Threat [] Other [] COMMENTS:

REFERENCES:

MAP (Indicate North)

13 8 36 9



We find test : North

301 303	Side yard of row house facing Eighth Street. 5X4 apartment building with pedimented cornice, matches styl
205 10	on West Side (See below)
305-19 321	Continuous row of 5X4 Italianate buildings with brick course Same scale as 805-19; slightly shorter with rough finished
323	brownstone lintels. Joseph F. Brandt Public School (#2) (see individual form)
VEST SI	DE
300,02	5X5 altered S.F. with pediments in second and third story li
304	pediment in cornice. 5X4 same details as 802.
304 306-10	2X3 Italianate segmental arch lintels; different lintels #81
312,14	3X2 Italianate; long second story windows.
316	3X3 Italianate with segmental arch lintels.
318-24	3X2, similar to 816
326	Vacant
328	3X3 particularly tall, italianate.
330	Deeply set back from street; aluminum siding.
	(832 nonexistant)
334	2X3 shingle front with garage connected to 836.
336	Altered front; crank-out windows
338,40	Italianate; 838 altered with applied false brick.
342	5X4 yellow brick; plaques below cornice; Classical Revival.
344	4X4 with altered S.F.

THREATS TO SITE: Fords [] Development [] Detectors time [] Detectors time [] Months and Conserve [] Cons

REFERENCES:

ORLY OR HISTORIC SECTEMATION" TOO HEEL SIVIE ZIFERI



800, 804 Park Avenue neg. #18-1



806, 808, 810 Park Avenue neg. #18-2



812, 814, 816 Park Avenue neg. #18-3



818, 820, 822, 824 Park Avenue neg. #18-4



828 Park Avenue neg.#18-5



830, 832, 834 Park Avenue neg. #18-6



836, 838, 840 Park Avenue neg. #18-7



840(part), 842, 844 Park Avenue neg. #18-8

NEW

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # STREETSCAPE SURVEY FORM

STREET NAME: Park Avenue

MUNICIPALITY: Hoboken

CROSS STREETS: Ninth and Tenth Streets

COUNTY: Hudson

DESCRIPTION/SIGNIFICANCE: Three story buildings on south third of East Side and most of West Side of block. Basic material is brick; basic condition of this neighborhood is below nearby blocks on Bloomfield and Garden Streets because of presence of tenements. Almost half of buildings are five stories.

Intact details:

Railings: 910, 13, 19, 21-23, 25, 27, 29, 31, 33 Fences: 911, 13, 19.21-23, 25, 27, 29, 31, 33

Doorways: 904, 07, 09, 10, 13, 14, 19, 21, 24, 27, 31-33, 35

PHYSICAL CONDITION OF SITES: E.cellent 35% Good 40% Fair 25% Poor REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [X] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration [] No Threat [] Other [] COMMENTS:


REFERENCES:

MAP (Indicate North)

1 1

1. 640 W.

11.2 48



BAYS, STORIES (TIX DI) OTHER MOTTAVAREZET DIROTERA TO SDIEGO VERNE WAS STOREFRONT (S.F.) MUNICIPALITY:

- Segmental arch lintels; 4x3 altered S.F. 901
- 3x3 segmental arch lintels; cornice identical to 901. 903
- 905 3x3 flat lintels, cornice identical to 901,03.
- 907-09 3x2 Italianate; 907 aluminum siding; 909 permastone and intact lintels.
- 911-13 3x2 pair; curved lintels; cornice matches 901,03,05.
- 915 boarded up. 915 - 17
- 919 5x4 pediment and cornice.
- 921-27 Four 5x4 matching units with festoons in cornices.
- 929 Non existent,
- 931-35 Three 4x4 units; cornice and lintels much like 919.
- 933 Cornice covered
- 937 Side of building facing Tenth Street.

WEST SIDE

- 900-04 Italianate; segmental arch lintels; altered S.F. on 900.
- 902 Has covered cornice.
- 904 Has parapet
- 906 Garage in vacant lot.

(dire Y stantint) TAM

- 908 4 story paired and single windows
- 910-14 3x3 Italianate; 914 almost intact; 912 permastone.
- 918 fenestration altered; only 922 has intact details; others 916-22 refaced in yellow brick.
- 924 3x3 permastone
- 926,28 Two 3x2 buildings; segmental arch lintels.
- 930 3x3, four story including basement.

roller [] Deterforation

- 932 Same as 930 but with segmental arch lintels; entrance intact.
- 934 Five story apartment building with intact copper (.S.F.) cornices Massive copper top cornice. THEREATS TO SETEN Roads [] Development

REFERENCES:

No Threat

3 rentso



900, 902, 904, 906(garage) Park Avenue neg. #27-12



neg. #27-13



906(set back), 908 Park Avenue neg. #27-14



910, 912, 914 Park Avenue neg. #27-15



916,918, 920 Park Avenue neg. #27-16



922, 924, 926, 928 Park Avenue neg. #27-17



928, 930, 932 Park Avenue neg. #27-18



934, 938 Park Avenue neg. #27-19





937 Park Avenue neg. #29-27





935, 933 Park Avenue neg. #29-26



931- 927 Park Avenue neg. #29-25



925, 923 Park Avenue neg. #29-23



921, 919 Park Avenue neg. #29-21



917, 915, 913, 911 Park Avenue neg. #29-19



909, 907, 905, 903 Park Avenue neg. #29-18



903, 901 Park Avenue neg. #29-14(16)

NEW

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY STREETSCAPE SURVEY FORM

STREET NAME: Park Avenue MUNICIPALITY: Hoboken

CROSS STREETS: Tenth and Eleventh Streets

COUNTY: Hudson

DESCRIPTION/SIGNIFICANCE:

Many three story row houses mixed with four and five story tenement buildings. Basic character of street has varied cornice lines and no continuous rowhouse pattern. Material is brick except in two cases. (1027,29).

1000, 1002, 1004, 1006, 1010, 1016-19, 1026, 1028-35 Intact rails: Fences: 1006, 1010, 1016-19, 1029, 1031-35 Doorways: 1002-10, 1012-20, no 22?, 1026, 1028, 1030, 1024, 1032-34 1036, 1038, 1040, 1042-Corner

PHYSICAL CONDITION OF SITES: E.cellent60 % Good 40% Fair Z Poor REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [x] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration [] No Threat [X] Other [] COMMENTS:


REFERENCES:

MAP (Indicate North)

3.40

The course of the

2 C 28 2 2 1



STORY,	STREETSCAPE SURVEY FORM
STOREFRO	ONT (S.F.)
	addition of the control of the contr
1001,03 1005	Side of building faces Tenth. Vacant lot
1007,09	Italianate, 3X2 with curved segmental arch lintels; altered
	stairways; 1009, altered windows.
1011,13	5x4 Italianate; pediments over doorway; brick checkerboard
	panels under windows.
1015	Non existent.
1017	Almost totally intact; 3x3 with pier-like brick panels
	separating windows.
1019	Non existent.
1021	5x5 second Renaissance Revival; stone and brick; arch-top wind.
1023,25	3x2 Italianate; segmental arch lintel.
1027	Painted brownstone; 3x2 lintels, shaved.
1029	4x3 brownstone; pediment over door.
1031-35	
	root and three Note: Morragetta parels on first stary

WEST SIDE

1037

1039

1000 Curved lintels; intact S.F. cornice; 3x3.
1002-10 3x2; foliate patterns on lintels
1012,16,20 Three tenement buildings; brick with pierlike panels corbelled above brownstone first story.

1014,18,22 Non existent

3x3

1024 3x3 rowhouse with bracketed, rough faced lintels.

1026-30 Three 3x2 rowhouses with identical cornices. Height identical to 1024. 1026 and 1028 have incised flower and foliate pattern in lintels; 1030 has rough-faced lintels.

rest are three. Note: Terracotta panels on first story.

Intact S.F.; five stories, faces Eleventh Street.

1032,34 3x3 Italianate; applied false brick on 1034.

1036 3x3 classical revival. Mary Stevens Hammond Memorial Home for Children.

1038 3x3 elaborate cornice.

1040 Intact S.F.

(Triblem e Morth)

1044 Five story apartment building faces Eleventh Street.

E80,

NESSERVATION,

REFERENCES:



1000, 1002, 1004 Park Avenue neg. #27-20



1006, 1008, 1010 Park Avenue neg. #27-21



1008, 1010, 1012, 1016, 1020 Park Avenue neg. #27-22



1020 Park Avenue neg. #27-23



1024, 26, 28, 30 Park Ave. neg. #: 21-24



1032,34 Park Ave. neg. #: 27-25



1036, 38 Park Ave. neg. #: 27-26



1040 Park Ave. neg. #: 27-27



1038, 40, 44 Park Ave. neg. #: 27-28



1039 Park Ave. (219 Eleventh St.) neg. # 30-5



1037 Park Ave. neg. # 30-4



1035,33,31 Park Ave. neg. # 29-36



1029,27 neg. # 29-33



1025,23 Park Ave. neg. # 29-32



1021-1017 neg. # 29-31

EAST SIDE



1013,1011 Park Ave. neg. # 29-30



1009,1007 Park Ave. neg. # 29-29



1013, 1011, 1009, 1007, 1005 (vacant) and 1003, 1001 neg. #29-28

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY STREETSCAPE SURVEY FORM



STREET NAME: Park Avenue MUNICIPALITY: Hoboken

CROSS STREETS: Eleventh and Twelfth Street

COUNTY: Hudson

DESCRIPTION/SIGNIFICANCE:

The block is notable for intact rowhouses, apartment buildings The south end of both sides of the street has the sides of nd detailing. owhouses that face Eleventh Street, so that the streetscape of this block starts at the eighth lot on both sides of the street and continues to twelfth treet.

The EAST SIDE has a continuous row of 2x3 rowhouses with high All stair rails and fences are intact (with the exception of 1127 basements. and 1129).

The WEST SIDE has a continuous row of five - five story, bay-windowed apartments along more than half the block; the remainder are two story brownstone rowhouses with high basements and one brick building. All fences and stair rails are intact.


Intact Doorways: 1106,07,08,09,10,11, 12, 19,20,22,23,24,31,33,35,39

PHYSICAL CONDITION OF SITES: E.cellent 85 % Good 15% Fair REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [x] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration [] No Threat [v] Other [] COMMENTS:

REFERENCES:

MAP (Indicate North)

1. P . . .



STORY, BAYS (X)

STOREFRONT (S.F.)

1101-05 Side of building facing Eleventh, with open lot at 1105.
1107-41 Have nearly identical cornices, with a few exceptions. Rangerom 1107-29 is 12 units that form a coordinated row. Pattern is as follows: A B C C D A A B C C B A. A-1107,17,19,29 - round arched windows in second story; 1107,29 - raised cornices 1117,19 - raised cornices and these two facades share pediment. B-1109,15,21,27 - flat lintels. C-1111,13,23,25 - segmental arch brick lintels connected by brick coursing. 1131-41 - incised flower in keystone of first story lintel; elaborate arched motif in second story windows; raised cornice 1141; covered cornice 1139.

NEW JERSEY OFFICE OF HISTORIC

STREETSCAPE SURVEY FORM

SIVIE

TOO HEST

BEFEROES:

HISLORIC SERRERAVIOR

EMAINOMEMBATYT

WEST SIDE

1100-04 Building facing Eleventh Street.

1106-14 Five 5 story apartment buildings, each with tripartite window bays flanking single windows; simplified Classical Revival.

Massive continuous copper cornice adds to overall appearance that this is one large complex.

1116-26 Brownstone; only 1120 and 1122 remain fully intact. 1116, 1118, 1126 stucco finish over first and second stories.

1124 Permastone.

filtron and bill the

1128 3x3 Italianate intact S.F. cornice.

PHISICAL COMDITION OF SITES: E de'ient 2 Good I: Fair I Boor I RECISTER ELIGIBILITY Faz | | Possible | Bo [:] Fart of larger Starrict INDERST TO SITE: Noeds |], Doveloped: [:] Zonfra [:] Desertoration [:] No Threat [:] Other [:]

No Threat [:] Other [:]



250 Eleventh 1100 + Park Ave. neg. #: 30-6

1108 Park Ave. neg. #: 30-8





1112, 14 Park Ave. neg. #: 30-9



1116, 18, 20 Park Ave.
neg. #: 30-10



1122, 24, 26 Park Ave. neg. #: 30-11



1124, 26, 28 Park Ave. neg. #: 30-12



1141,39,37 Park Ave. neg. # 25-14





1135,33,31 Park Ave. neg. #25-15



1129,27,25 Park Ave. neg. #25-16



1123,21,19 Park Ave. neg. #25-18



1123,21,19,17,15,13 Park Ave. neg. #25-17



1117,15,13,11 Park Ave. neg. #25-19



1111,09,07 Park Ave. neg. #25-20



1105-1101 Park Ave. neg. #25-21



1101 Park Ave. neg. #25-22

08625

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY STREETSCAPE SURVEY FORM

STREET NAME: Park Avenue MUNICIPALITY: Hoboken

CROSS STREETS: Twelfth and Thirteenth STS

BOTE TRAS . hyper

COUNTY: THudson II-109

fine bru nedime

TOWNStone

DESCRIPTION/SIGNIFICANCE:

(A) A

at have al

The WEST SIDE of the block has a continuous range of three story x three bay rowhouses that are marred only by some alterations of doors, stairways, rails, fences and cornices.

The EAST SIDE has a row of five story apartments in addition

to a row of brownstones of mostly 3x2 size.


The neighborhood has a very active streetlife and a neat character. Basic material is red brick.

ad ad

The cornice at each PHYSICAL CONDITION OF SITES: E.cellent 90 % Good 10% Fair % Poor % REGISTER ELIGIBILITY: Yes [] Possible [X] No [] Part of larger district [X] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration [] No Threat [x] Other [] COMMENTS: TOT - 8

REFERENCES:

(Indicate North)



STORYX OTBAYS (ST X 3) SOTETH MOTTAVASERY STROTERS TO SSIERCE SERVICE STROTE ST

STOREFRONT (S.F.)

CROSS, STREETS:

1201-11 Cornices identical; particularly fine rails and fences; 12 ·0 brownstone 3x3, has three part window arrangement. 1211 brownstone first story, brick with brownstone trim and courses; fine broken pediment over door

STREETSCAPE SURVEY FORM

1213-27 3x3 brownstone rowhouses, virtually identical, although string course over first story windows is higher (directly undersecond story windows) at 1217; 1221 altered with permastone, cornices are identical.

1229-35 Four 5 story apartment buildings, yellow brick, each with two bay windows flanking a single window in each story. Massive copper cornice (painted green at 1233 and 1235).

1237 Faces Thirteenth Street.

WEST SIDE

A continuous range of rowhouses with two basic designs in the following pattern:

(Those facades which are altered are in parentheses; the design can be presumed based whe overall pattern and despite total alteration in some cases.)

0 2 4 6 8 10 12 14 16 18 20 22 24 26 28 30 32 34 36 38 40 A B A A B A A B A (A) B A

The cornices at each end of the range differ slightly from 11 the rest. A has protruding stone lintels that have aba (flat, pedia nt flat) pattern in second story and curved pediment in cornices. A has bab pattern in second stories. B has brick courses connecting brick segmental arch lintels, carved heads in keystone of all lintels, and triangular pediments in the cornices.

Alterations: 1210,16 - applied false brick; 1218 - permastome; 1206,8,14 - covered cornices,

Lay they the to be the promise of

MAP (Indicate North)

Remain,

FERENCES:



1200, 02, 04, 06 Park Ave. neg. #: 30-13



1200, 02, 04 Park Ave. neg. #: 30-14

 \langle



1206, 08, 10 Park Ave. neg. #: 30-15



1212, 14, 16 Park Ave. neg. #: 30-16



1218, 20, 22 Park Ave. neg. #: 30-17



1224, 26, 28 Park Ave. neg. #: 30-18



1230, 32, 34 Park Ave. neg. #: 30-19



1236, 38, 40 Park Ave. neg. #: 30-20



1247-1237 Park Ave. neg. # 25-5



1235,1233 neg. # 25-5



1235,33,31,29 neg. # 25-6



1231,29 Park Ave. neg. # 25-7

1227,25,23,21 neg. # 25-8





1221,19,17,15 Park Ave. neg. # 25-9

1217,15,13,11 neg. # 25-10





1209,07,05 Park Ave. neg. # 25-11

1205,03,01 neg. # 25-12



NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # STREETSCAPE SURVEY FORM

CROSS STREETS:

COUNTY:

DESCRIPTION/SIGNIFICANCE:

STREET NAME: MUNICIPALITY:

7 Poor REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration []

> (Indicate North) 1306 15087 15 Aug PARK AVE CLOTHING

WEST SIDE



1300 Park Ave. neg. #. 30-21



1302 Park Ave. neg. #: 30-22



1304 Park Ave. neg. #: 30-23



1321 Park Ave. neg. # 25-1



1319,1317 meg. # 25-2



photo date: 11-20-78

1301 neg. # 25-3 NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # STREETSCAPE SURVEY FORM CROSS STREETS: STREET NAME:

COUNTY:


DESCRIPTION/SIGNIFICANCE:

MUNICIPALITY:

7 Poor REGISTER ELIGIBILITY: Yes [] Possible [] No [] Part of larger district [] THREATS TO SITE: Roads [] Development [] Zoning [] Deterioration []

(Indicate North)







1415 Park Ave.
U.S. Testing Co., Inc.
neg. #: 35-35