

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # 17-13
INDIVIDUAL STRUCTURE SURVEY FORMHISTORIC NAME: St. Joseph's School
LOCATION: 73 (73-77) Jackson St.COMMON NAME: Same
BLOCK/LOT 15/5MUNICIPALITY: Hoboken
USGS QUAD:
OWNER/ADDRESS:COUNTY: Hudson
UTM REFERENCES:
Zone/Northing/Easting

DESCRIPTION

Construction Date: (founded 1882)

Source of Date:

Architect:

Builder:

Style: Classical Revival

Form/Plan Type:

Number of Stories: 3

Foundation:

Exterior Wall Fabric:

Fenestration: 5 bays, paired wood double hung with elaborate mullions and transoms in 1st story. Jalousies in 2 top stories (except center Roof/Chimneys: bay which has arched transom in 2nd story).

Additional Architectural Description:

Ionic capitals of columns flanking entry voussoirs in lintels. Center bay protrudes with pediment in metal cornice. Brick "Quoins" on center bay and corners.

Map (Indicate North)

photo date: 11-2-78



SITING, BOUNDARY DESCRIPTION, AND RELATED STRUCTURES:

Next to convent, across from factory

SURROUNDING ENVIRONMENT: Urban ☐ Suburban ☐ Scattered Buildings ☐
Open Space ☐ Woodland ☐ Residential ☒ Agricultural ☐
Industrial ☒ Downtown Commercial ☐ Highway Commercial ☐ Other ☐

SIGNIFICANCE:

ORIGINAL USE: School

PHYSICAL CONDITION: Excellent ☐ Good ☒

REGISTER ELIGIBILITY: Yes ☐ Possible ☐

THREATS TO SITE: Roads ☐ Development ☐

No Threat ☒ Other ☐

COMMENTS:

PRESENT USE: School

Fair ☐ Poor ☐

No ☐ Part of District ☒

Zoning ☐ Deterioration ☐

REFERENCES:

RECORDED BY: J. P. Sholeen
ORGANIZATION:

DATE: 11-1-78

NEW JERSEY OFFICE OF HISTORIC PRESERVATION HISTORIC SITES INVENTORY # 17-14
INDIVIDUAL STRUCTURE SURVEY FORMHISTORIC NAME: St. Joseph's convent
LOCATION: 69 (69-71) JacksonCOMMON NAME: Same
BLOCK/LOT 15/5MUNICIPALITY: Hoboken
USGS QUAD:
OWNER/ADDRESS:COUNTY: Hudson
UTM REFERENCES:
Zone/Northing/Easting

DESCRIPTION

Construction Date:

Source of Date:

Architect:

Builder:

Style: Classical Revival

Form/Plan Type:

Number of Stories: 3

Foundation:

Exterior Wall Fabric: Orange brick

Fenestration: 3 bays. Double hung aluminum, stained glass top story
2 story protruding bays either side of entry.

Roof/Chimneys:

Additional Architectural Description:

Much (false?) stone used - especially over windows with false key-stones in lintels. Rusting cornice but otherwise good condition.



Map (Indicate North)

Photo date: 11-2-78

SITING, BOUNDARY DESCRIPTION, AND RELATED STRUCTURES:

Next to St. Joseph's School - across from 4 story factory.

SURROUNDING ENVIRONMENT: Urban ☐ Suburban ☐ Scattered Buildings ☒
Open Space ☐ Woodland ☐ Residential ☒ Agricultural ☐
Industrial ☒ Downtown Commercial ☐ Highway Commercial ☒ Other ☐

SIGNIFICANCE:

ORIGINAL USE: Convent

PHYSICAL CONDITION: Excellent ☐ Good ☒

REGISTER ELIGIBILITY: Yes ☐ Possible ☐

THREATS TO SITE: Roads ☐ Development ☐

No Threat ☐ Other ☐

COMMENTS:

PRESENT USE: Convent

Fair ☐ Poor ☐

No ☐ Part of District ☐

Zoning ☐ Deterioration ☐

REFERENCES:

RECORDED BY: J. P. Sholeen
ORGANIZATION: CDA

DATE: 11/1/78